

ACTCAP Wire Connector CAT No. AL-ACS-BL-(C,M)

To be sold only with installation instructions

Installation Instructions

1. Turn off power before installing or removing connectors.
2. Strip wire 3/8" (9.5 mm). For #16 and smaller wires, strip 1/2" (12.7 mm).
3. Pre-twisting unnecessary. Hold stripped wires together with ends even.
Lead stranded wires slightly.
4. Align any frayed strands or conductors.
5. Push wires into connector and screw on until two twists are visible in wires.

FOR USE WITH COPPER TO COPPER

Temperature Rating: 105 °C (221 °F) Max.

Voltage Rating: 300V Max.

Listed as a Pressure-Type Wire Connector on the following **Solid** and/or **Stranded** wire combinations:

For UL Listed and CSA Certified

- | | |
|------------------------------|----------------------------|
| 1 #14 | 2 #16 w/1 #18 |
| 1 to 3 #16 | 2 #16 w/1 or 2 #20 |
| 1 to 4 #18 | 2 #16 w/1 #20 w/1 #22 |
| 3 to 5 #20 | 2 #16 w/1 to 3 #22 |
| 2 #22 | 1 #18 w/1 to 4 #20 or #22 |
| 1 #14 w/1 #16 | 1 or 2 #18 w/1 #20 w/1 #22 |
| 1 #14 w/1 or 2 #18 | 2 #18 w/1 to 3 #20 or #22 |
| 1 #14 w/1 to 3 #20 or #22 | 3 #18 w/1 or 2 #20 or #22 |
| 1 #16 w/1 to 3 #18 | 4 #18 w/1 #22 |
| 1 #16 w/1 #18 w/1 #20 | 3 #20 w/1 or 2 #22 |
| 1 #16 w/1 to 4 #20 or #22 | 4 #20 w/1 #22 |
| 1 #16 w/1 #22 w/1 #18 or #20 | |

Contact Industrial Hardware & Specialties
with your wire accessory needs.
973-684-4010
industrialhardware.com

